```
=> d his ful


        FILE 'REGISTRY' ENTERED AT 13:11:13 ON 07 AUG 2006
                E AMMONIUM HYDROXIDE/CN
L1          1 SEA ABB=ON   PLU=ON   "AMMONIUM HYDROXIDE"/CN
                E  POTASSIUM HYDROXIDE/CN
L2          1 SEA ABB=ON   PLU=ON   "POTASSIUM HYDROXIDE"/CN
                E CALCIUM HYDROXIDE/CN
L3          1 SEA ABB=ON   PLU=ON   "CALCIUM HYDROXIDE"/CN
                E BARIUM HYDROXIDE/CN
L4          1 SEA ABB=ON   PLU=ON   "BARIUM HYDROXIDE"/CN
                E LITHIUM HYDROXIDE/CN
L5          1 SEA ABB=ON   PLU=ON   "LITHIUM HYDROXIDE"/CN
                E STRONTIUM HYDROXIDE/CN
L6          1 SEA ABB=ON   PLU=ON   "STRONTIUM HYDROXIDE"/CN
                E RUBIDIUM HYDROXIDE/CN
L7          1 SEA ABB=ON   PLU=ON   "RUBIDIUM HYDROXIDE"/CN
                E CESIUM HYDROXIDE
                E CESIUM HYDROXIDE/CN
L8          1 SEA ABB=ON   PLU=ON   "CESIUM HYDROXIDE"/CN
L9          8 SEA ABB=ON   PLU=ON   (L1 OR L2 OR L3 OR L4 OR L5 OR L6 OR L7 OR
                L8)
L10         7 SEA ABB=ON   PLU=ON   L1 OR (L3 OR L4 OR L5 OR L6 OR L7 OR L8)
                E 1,3-PROPANEDIOL/CN
L11         1 SEA ABB=ON   PLU=ON   "1,3-PROPANEDIOL"/CN



        FILE 'CAPLUS' ENTERED AT 13:28:37 ON 07 AUG 2006
L12      3811 SEA ABB=ON   PLU=ON   VISCOSITY/OBI (L) (DECREAS?/OBI OR
                REDUC?/OBI )
L13     83241 SEA ABB=ON   PLU=ON   L9
L14        35 SEA ABB=ON   PLU=ON   L12 AND L13
L15     60225 SEA ABB=ON   PLU=ON   L13 (L) (MOA OR RGT OR RACT OR USES)/RL
L16        31 SEA ABB=ON   PLU=ON   L15 AND L14
L17     35160 SEA ABB=ON   PLU=ON   L2
L18        19 SEA ABB=ON   PLU=ON   L17 AND L12
L19        14 SEA ABB=ON   PLU=ON   L16 NOT L18
L20      2441 SEA ABB=ON   PLU=ON   ALKALINE/OBI (W)   ( EARTH/OBI OR METAL/OBI)
                (W)  HYDROXIDE#/OBI
L21         3 SEA ABB=ON   PLU=ON   L20 AND L12
L22        32 SEA ABB=ON   PLU=ON   L16 OR L21
L23        15 SEA ABB=ON   PLU=ON   L22 NOT L18
                E HYDROFORMYLATION/CT
                E E3+ALL
L24      6563 SEA ABB=ON   PLU=ON   HYDROFORMYLATION#/OBI
L25         4 SEA ABB=ON   PLU=ON   L24 AND L20
L26         1 SEA ABB=ON   PLU=ON   L24 AND L12
L27         5 SEA ABB=ON   PLU=ON   L25 OR L26
L28         5 SEA ABB=ON   PLU=ON   L27 NOT (L23 OR L18)
L29       334 SEA ABB=ON   PLU=ON   KNIFTON J?/AU
L30      1096 SEA ABB=ON   PLU=ON   JAMES T?/AU
L31        41 SEA ABB=ON   PLU=ON   WEIDER P?/AU
L32      2320 SEA ABB=ON   PLU=ON   POWELL J?/AU
L33        34 SEA ABB=ON   PLU=ON   NEILSEN E?/AU
L34        13 SEA ABB=ON   PLU=ON   KOMPLIN G?/AU
L35      3792 SEA ABB=ON   PLU=ON   (L29 OR L30 OR L31 OR L32 OR L33 OR L34)
L36         2 SEA ABB=ON   PLU=ON   L35 AND L12
L37         8 SEA ABB=ON   PLU=ON   L35 AND L13
L38         1 SEA ABB=ON   PLU=ON   L35 AND L20
L39         9 SEA ABB=ON   PLU=ON   (L36 OR L37 OR L38)
```

L40	8 SEA ABB=ON	PLU=ON	L39 NOT (L18 OR L23 OR L28)
L41	5257 SEA ABB=ON	PLU=ON	L11
L42	32 SEA ABB=ON	PLU=ON	L41 AND L35
L43	1 SEA ABB=ON	PLU=ON	L42 AND L13
	D SCAN		
L44	0 SEA ABB=ON	PLU=ON	L43 NOT (L18 OR L23 OR L28 OR L40)

08/07/2006 Searched by Alex Waclawiw